

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#27

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

January 1, 1959

Subject: ENGINE - MODEL A-9

Description: OIL BREATHER CAP

Oil breather caps should be cleaned periodically to insure adequate crankcase ventilation.

Caps should be removed and soaked in a strong cleaning solution so that all oil and dust foreign particles are cleaned from the wire mesh cap.

For proper maintenance of the cooling system, it is suggested to completely drain and flush out engine blocks. Refill with clean water, using an approved rust inhibitor solution.

This will insure a clean passage throughout the engine and provide for adequate cooling.

By: NEW YORK SERVICE DEPARTMENT