

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#27

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

January 1, 1959

Subject: ENGINE - MODEL A-9

Description: OIL BREATHER CAP

Oil breather caps should be cleaned periodically to insure adequate crankcase ventilation.

Caps should be removed and soaked in a strong cleaning solution so that all oil and dust foreign particles are cleaned from the wire mesh cap.

By: NEW YORK SERVICE DEPARTMENT