

# SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#10

SUBSIDIARY OF  
CHECKER MOTORS  
CORPORATION

NEW YORK \* BROOKLINE  
CHICAGO \* DETROIT

January 1, 1959

Subject: BRAKES - MODEL A-9

Description: INSPECTION OF BRAKE CYLINDERS

Inspection of brake wheel cylinders and master cylinder should be completed during every brake service period.

Cylinder boots should be pulled back and inspected for possible fluid seepage.

Boots, pistons and cups should be removed completely whenever there is an indication of leaks and entire cylinder inner surface washed with a clean cloth immersed in brake fluid or alcohol. DO NOT USE GASOLINE OR NAPHTHA.

Brake hoses should be inspected for swollen fabric or spongy hose.

It is further recommended to drain entire fluid system after every 12 to 18 months, and refill with new brake fluid. This procedure will minimize the formation of gum in the brake lines and cylinders, as temperature changes and oxidation have a definite effect on brake fluids.

By: NEW YORK SERVICE DEPARTMENT