

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

Special #2

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

November 18, 1958

Subject: BRAKES - MODEL A-9
Description: SERVICE LINING REPLACEMENT

Model A-9 Checker cars when delivered from the factory are equipped with standard production brake lining.

It is recommended that on the first brake re-line, this original lining should be replaced with JM-1105 lining which has been very successful in past model cars, particularly in increased lining service life.

It is suggested that original brakes be inspected at 5,000-mile intervals and the JM service replacement lining installed as soon as original lining indicates excessive wear.

IMPORTANT

By: NEW YORK SERVICE DEPARTMENT