

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#13

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

January 1, 1959

Subject: STEERING - MODEL A-9

Description: POWER STEERING POWER FILTER CARTRIDGE

It is recommended that the power steering fluid filter cartridge be replaced at 25,000-mile intervals.

The following procedure for replacement should be used:

1. Remove oil reservoir clamp and cover.
2. Draw as much oil as possible out of reservoir with a suction gun.
3. Lift filter element out of reservoir.
4. Place new filter in reservoir and lay retaining spring seat on top of element, then install retaining spring.
5. Fill reservoir to proper level with approved Type A Automatic Transmission Fluid.
6. Install new seal on reservoir cover and tighten cover and clamp securely.

By: NEW YORK SERVICE DEPARTMENT