

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

#73

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

February 11, 1959

Subject: COOLING SYSTEM

Description: RADIATOR AND HEATER CORE MAINTENANCE

It is suggested that when storing radiator or heater cores for stock inventory, these should be filled with clear water, to which is added the recommended amount of rust inhibitor.

Cores stored in a dry condition will eventually develop a sulphation on soldered sections and result in possible separation of tank to core or tube to tank areas.

By: NEW YORK SERVICE DEPARTMENT