

SERVICE BULLETIN

CAB SERVICE & PARTS CORPORATION

Special #4

SUBSIDIARY OF
CHECKER MOTORS
CORPORATION

NEW YORK * BROOKLINE
CHICAGO * DETROIT

January 1, 1959

Subject: ENGINE - MODEL A-9


Description: SAFETY PRECAUTION

IMPORTANT

As an added safety precaution while completing adjustments to the engine or automatic transmission, it is very important that a stop block be placed at the front and rear wheels.

Stop blocks can be fabricated in your shop by cutting a block of wood 6" X 6" on a 45° angle.

This safety feature is in addition to applying the hand brake when adjustments are made in drive position to either the engine or transmission assembly.



By: NEW YORK SERVICE DEPARTMENT